

CONVERSION CHART - GAUGE / MM

By : Perles & Co

GAUGE	MM
0	8.26
2	6.54
4	5.19
6	4.12
8	3.26
10	2.59
12	2.05
14	1.63
16	1.29
18	1.02
19	0.912
20	0.812



0 minutes

GAUGE	MM
0	8.26
2	6.54
4	5.19
6	4.12
8	3.26
10	2.59
12	2.05
14	1.63
16	1.29
18	1.02
19	0.912
20	0.812
21	0.723
22	0.644
23	0.573
24	0.511
25	0.455
26	0.405
27	0.360
28	0.321
29	0.286
30	0.255
32	0.2019
34	0.1600

Result